

WatchDog Radiation Shield Product Manual

Item #3663

1. The Radiation Shield will ship in two sections (Part A and Part B)

2. Place your WatchDog A Series Data Logger inside Part B

4. Twist the top nuts on Part A counter clockwise by hand until they are tightened and the unit is fully assembled

3. Line up the screws in Part A with the threads in Part B

5. Fully assembled Radiation Shield

